





- is there a ,real' problem (e.g. partially blockage of a pipe)
- is this a sensor problem?













- similar decrease in input flow as in channel 9
- no change of pressure as in channel 9




- all flows and pressure mostly stable throughout 2015-2018













- similar decrease in input flow as in channel 9 (not as steep though)
- no change of pressure as in channel 9









- similar decrease in input flow as in channel 9
- slow increase of pressure by 15 mbar

Summary / Questions

- There seem to be some systematic decrease visible in the input flow
 - However some channels don't show that
 - Is that change real?
- What's the nature of the issue seen in channel 64/09?
 - partially blockage of a pipe?
 - The flow impedances are very small; could be partially blocked by dirt
 - Is the pressure sensor ,healthy'?
- Next steps
 - Measuring the flow through individual chambers next week
 - Looking at other racks