



# Results on Stripping Foil Tests


C. Bracco, L. Jorat, R. Noulibos, P. Van Trappen and **W. Weterings**

Acknowledgment: Linac4 and PSB-OP teams





# Test Conditions - BCT



Downstream  
Beam Current  
Transformer (BCT)

Stripping Foil Test-stand  
(TKSTR)

Transfer Line to  
Proton Synchrotron  
Booster (PSB)

Quadrupole LMQF.0210  
to switch off when  
stripping foil IN

Upstream  
Beam Current  
Transformer (BCT)

Two cross-calibrated beam current transformers (BCT), located upstream and downstream of the foil, are used to measure the stripping efficiency by looking at their relative current decrease.






# Stripping Foil Test Stand – from INTDS2014

## Conceptual Design

J. Radioanal. Nucl. Chem. (2015) 305: 831.  
doi:10.1007/s10967-014-3917-0




# Stripping Foil Exchange Mechanism (TKSTR)

UHV compatible  
Kapton® cabling

UHV compatible  
micro switches


membrane  
potentiometers



rotating stainless steel  
belt for 6 holders


Ceramic cable guides

holder with stripping  
foils attached






# Stripping foil Test stand (TKSTR Inside tank)






# Test Conditions – Setting up with BTV






# Test Conditions – Setting up with BTV





# Test Conditions – Setting up with BTV



Beam spot on BTV screen, acquisition interface image








# Test Conditions - BCT

Downstream  
Beam Current  
Transformer (BCT)



Upstream  
Beam Current  
Transformer (BCT)


Two cross-calibrated beam current transformers (BCT), located upstream and downstream of the foil, are used to measure the stripping efficiency by looking at their relative current decrease.






# Stripping Foils Tested with Beam


Foil #	Description	Thickness	Reference	Beam Time
1	Arc evaporated amorphous Carbon	200 $\mu\text{g}/\text{cm}^2$	XCF-200	Autumn 2017 → Spring 2018
2	Arc evaporated amorphous Carbon	199 $\mu\text{g}/\text{cm}^2$	GSI-199	Autumn 2018
3	Multilayer Graphene	233 $\mu\text{g}/\text{cm}^2$	MLG-233	Autumn 2018
4	Arc evaporated amorphous Carbon	200 $\mu\text{g}/\text{cm}^2$	XCF-200	Autumn 2018
5	Diamond-like Carbon	200 $\mu\text{g}/\text{cm}^2$	DLC-23-1000-S	Autumn 2017 → Autumn 2018
6.1	Multilayer Graphene	200 $\mu\text{g}/\text{cm}^2$	MLG-200	Autumn 2017 → Spring 2018
6.2	Multilayer Graphene	251 $\mu\text{g}/\text{cm}^2$	MLG-251	Autumn 2018



XCF-200



XCF-200



GSI-199



MLG-233



DLC-23-1000-S




# Test Conditions – Beam Characteristics

	Autumn 2017	Spring 2018	Autumn 2018
Repetition rate [s]	1.2	1.2	1.2
Beam pulse length [ $\mu$ s]	150-600	150-600	600*
Average pulse current [mA]	~15	5-20	15*

\*Nominal chopping pattern (650/350)



# Test Results – Stripping Efficiency



Beam time:





# Test Results – Observation #1

INTDS2016; AIP Conference Proceedings 1962, 030003 (2018)

Since improvement of the electrical contacts of the foil holders and application of a silver conducting layer on the backside of the BTV screen this phenomena has not anymore been observed.

01/11/2016 14:36h  
Seems foil got broken -  
due to radiant heat from  
BTV screen? - right after  
putting the BTV screen in  
for ~2min with beam.  
Efficiency not affected  
since rupture is rather at  
the right-hand side.

03/11/2016 15:56h  
Foil #5 broken! It has  
disappeared completely.  
Also some vacuum activity  
visible.  
It happened while we moved  
OUT the BTV screen (beam  
was kept ON).






# Test Results – Observation #2

10/11/2017 15:58h  
Foil #5, DLC-23-1000-S,  
movement of the foil is  
observed at every beam  
shot (like a heartbeat).  
Foil in for ~ 5 minutes.  
BCT.LAZ value 100%






# Stripping efficiency evolution – DLC-23-1000-S





# Stripping efficiency evolution – DLC-23-1000-S







# Test Results – Observation #3

24/04/2018 08:05h  
Removed foil #5 from  
beam, foil visually in  
same condition as last  
night. [WWW], inspection  
of other foils, foil #2,  
DLC-23-1000-S, has  
disappeared from frame....



This foil has not been in the beam position, nevertheless it was completely removed from the foil holder.





## Test Results – Observation #3




It was found lying inside the vacuum tank and looked completely burnt. We notice delamination of the foil layers at the edge of the foil. The foil holder of this particular foil was very activated,  $> 38 \mu\text{Sv}$  at contact, compared to  $0.1 \mu\text{Sv}$  of all other frames.





# Test Results – Observation #3

## Hypotheses




Logbook entries show that during the low energy tuning @ 3MeV, the beam was not properly steered and was lost just upstream of the TKSTR, causing showers on the foil holder. This was confirmed by damage to downstream electronics.

24/04/2018 08:05h  
 Removed foil #5 from beam, foil visually in same condition as last night. [WWW], inspection of other foils, foil #2, DLC-23-1000-S, has disappeared from frame....

Standard frame  
 0.1  $\mu\text{Sv}$  contact  
 0.1  $\mu\text{Sv}$  @ 10cm

Impacted frame  
 38  $\mu\text{Sv}$  contact  
 3  $\mu\text{Sv}$  @ 10cm





# Test Results – Observation #4



26/09/2018 19:03h  
Preparing stripping foil  
tests. L4T.RQF.021  
disabled. Image of beam  
on screen.  
Unfortunately the screen  
is **BROKEN!**  
Re-enable L4T.RQF.021

Probably due to high stress during tests to check that improved grounding solved issues with broken foils due to BTV charging/movements (~5 minutes with high intensity beams, BTV and foil IN)





# Test Results – Observation #5

27/09/2018 19:05h  
Foil\_2, GSI\_199. After 1  
beam pulse the foil  
completely changed  
aspect. It looks like the  
foil shrunk, or stressed  
towards the centre.  
Nevertheless, no changes  
in efficiency.




After only one 600 $\mu$ s pulse, 4x150 $\mu$ s @19.7mA, the foil completely deformed. No influence on performance, the foil remained in beam for 12 hours with stripping efficiency of ~99.8%.





# Stripping efficiency evolution – GSI-199

No signs of stripping efficiency degradation despite crater



# Summary

- The test stand proved to be extremely useful in providing operational experience and knowledge with the stripping foils and the related diagnostics
  - Beam and foil setup using BTV screen
  - BTV interlock logic + grounding to prevent foil breakage
  - Cross-calibrated BCTs
- All foils are characterized by a stripping efficiency better than 98%
  - Also foils presenting evident deformation did not show any worsening in performance
  - Multi-layer graphene foils reach 99% stripping efficiency when thickness  $\geq 233 \mu\text{g}/\text{cm}^2$  → very easy to mount!  
Emittance blow up?
  - Stripping efficiency mainly affected by steering and quad on/off
  - No clear correlation between stripping efficiency and beam losses
- Damages:
  - Foils mainly broken due to mechanical movements or BTV charging
  - Burnt foil probably due to radiation during energy tuning
  - BTV broken probably as a consequence as too high energy deposition during tests to evaluate effectiveness of grounding
- Preliminary conclusions: presently not clear preference for one type of foils (equivalent performance for different advantages in terms of cost, handling, etc.) → different foils in the PSB injection region → evaluate effect on beam emittance, beam losses and life time in real operational conditions → final decision