



The Nuts and Bolts Affecting Accelerator Reliability

Andreas Stolz

NSCL / Michigan State University

Accelerator Reliability Workshop 2017


Versailles, October 2017



- **Located at Michigan State University in East Lansing, Michigan, USA**
- **National user facility for rare isotope research and education in nuclear science, astro-nuclear physics, accelerator physics, and societal applications**
- **One of the three nuclear-science flagship facilities in the US: RHIC at BNL, CEBAF at JLAB, NSCL at MSU [2007 NSAC Long Range Plan]**
- **Largest university-based nuclear physics laboratory in the United States: 10% of U.S. nuclear science Ph.D.s**
- **Over 500 employees (NSCL+FRIB), incl. 103 graduate students, and 45 faculty – user group with 1350 members**
- **Graduate program in nuclear physics ranked 1st [U.S. News and World Report]**
- **NSCL provides accelerated beams of heavy ions from oxygen to uranium, including rare isotope beams**
- **Michigan State University has been selected to establish FRIB, the Facility for Rare Isotope Beams**



Coupled Cyclotron Facility at NSCL



2 ECR ion sources

2 coupled cyclotrons: K500 + K1200

primary beams: oxygen to uranium

K500: 8 - 14 MeV/u, 2-8 e μ A

K1200: 100 - 170 MeV/u, up to 2 kW

A1900 fragment separator

to produce rare isotope beams

by projectile fragmentation

power limit beam dump in first dipole: 4kW

NSCL Primary Beam List

Primary beam list intensities are based on operational experience and serve as planning basis for experiments.

Usually, beam intensities above these values are provided to the experiment.


Beam power for Ca-48: 540 W

Isotope	Energy [MeV/u]	Intensity [pnA]	Isotope	Energy [MeV/u]	Intensity [pnA]
¹⁶ O	150	175	⁸² Se	140	35
¹⁸ O	120	150	⁷⁸ Kr	150	25
²⁰ Ne	170	80	⁸⁶ Kr	100	15
²² Ne	120	80	⁸⁶ Kr	140	25
²² Ne	150	100	⁹⁶ Zr	120	1.5
²⁴ Mg	170	60	¹¹² Sn	120	4
³⁶ Ar	150	75	¹¹⁸ Sn	120	1.5
⁴⁰ Ar	140	75	¹²⁴ Sn	120	1.5
⁴⁰ Ca	140	50	¹²⁴ Xe	140	10
⁴⁸ Ca	90	15	¹³⁶ Xe	120	2
⁴⁸ Ca	140	80	²⁰⁸ Pb	85	1.5
⁵⁸ Ni	160	20	²⁰⁹ Bi	80	1
⁶⁴ Ni	140	7	²³⁸ U	45	0.1
⁷⁶ Ge	130	25	²³⁸ U	80	0.2

CCF Primary Beam Isotope Statistics


Coupled Cyclotron Facility (CCF) delivers a different primary beam every 5 to 7 days, typically 30 beam changes per year.

The development of new primary beams (isotope and energy) is driven by user demand.




Rare Isotope Beams produced at NSCL

more than 1000 RIBs have been produced (2001-2017)
 more than 900 have been used in experiments



CCF Operations Hours



**NSCL operations hours:
typically: 4500 hours/year**

up to 6000 hours/year possible


During scheduled facility operations
NSCL operates on a 24/7 schedule.

Facility availability of more than
90% allows for reliable schedule
and high user satisfaction


**NSCL operations is certified
according to ISO 9001,
ISO14001, and ISO 18001**

NSCL's Experimental Facility Plan


NSCL is the only facility in the world that can provide fast, thermalized, and reaccelerated beams of rare isotope.



CCF Operations Availability



CCF Operations Availability



**“All men make mistakes, but only
wise men learn from their mistakes.”**

Winston Churchill


**“All men make mistakes, but only
wise men learn from their mistakes.”**

Winston Churchill

**“We don’t have the time to learn from our own mistakes,
we need to learn from other people’s mistakes.”**

*Thomas Glasmacher
(my big boss)*

Dipole Magnets in the A1900 Fragment Separator



A1900 fragment separator
to produce rare isotope beams
by projectile fragmentation



Superconducting Dipole Magnets
maximum current: 160 Amps
maximum field: 2 Tesla
Inductance: 45 Henry @ 100 Amps
maximum stored energy: 500 kJ
weight: 50 tons

A1900 Dipole Magnet 3 Failure

Electronic LogBook

galbrait, 11/3/15, 3:01 pm

Z071DS is out of LHe. Cryo is filling. Magnet Group is adjusting lead gas.

ginter, 11/3/15, 5:25 pm

We have been having trouble with Z071DS -- it quenched twice today.

ginter, 11/3/15, 5:39 pm

Z071DS has tripped again. This time it did not manage to ramp up to 110 A

beal, 11/3/15, 9:21 pm


Problems with Z071DS continue. John DeCamp and Robin Walker now feel the need to access the magnet's power supply.

rencsok, 11/3/15, 10:23 pm

General update regarding Z071DS. When power supply cabinet was opened for Z071DS we found one lead off it's connection.


bonofigl, 11/3/15, 11:13 pm

After further analysis, it appears there is damage to the magnet. Will schedule a repair team meeting for tomorrow morning to assess.



A1900 Dipole Magnet 3 Failure - Power Supply

Back of the power supply




During power supply replacement original stainless steel bolt was replaced with brass bolt in order to increase conductivity.

This bolt was found broken inside the power supply rack.

Stored energy in magnet: 137 kJ

A1900 Dipole Magnet 3 Failure - Power Supply




A1900 Dipole Magnet 3 Failure - Magnet Leads

Broken diagnostic wires



After removing the lead can it became obvious that superconducting lead wires were significantly damaged.

Magnet Leads Damaged beyond Repair




Spare dipole coil package just finished
 Damaged coil package was replaced with spare one.

Dipole replacement takes 4 week:

- warm-up superconducting magnet
- remove concrete roof beam shielding
- disassemble 40 ton iron yoke
- replace coil package
- assembly 40 ton iron yoke
- align magnet
- install concrete roof beam shielding
- cool-down magnet

Time Line

76 days

- 
- 11/03/2015 Magnet failure
 - 11/04/2015 Extent of damage realized, decision to warm up magnet
Decision to turn off all superconducting magnets to inspect bolt connections
 - 11/05/2015 Project plan with two options: Magnet Repair / Magnet Replacement
 - 11/06/2015 Decision to start winter maintenance shutdown 5 weeks early
 - 11/09/2015 Decision to replace magnet
 - 11/25/2015 Old magnet removed, new coil package and iron yoke installed
 - 12/10/2015 Cryo-welding completed
 - 12/29/2015 Magnet filled with liquid Helium
 - 01/05/2016 Magnet tested at 160 Amps
 - 01/18/2016 Magnet tested with beam, rho calibration

Identifying the Root Cause

This bolt was used

“Ornamental” Brass Bolt

Unknown material property



This bolt should have been used


Silicon-Bronze Hex cap bolt
Alloy 651 silicon bronze
(98.5% copper, 1.5% silicon)

Minimum tensile strength
tested according ASTM F468
to 50,000 psi.

Root Cause

Inadequate quality control of
power supply lead connections.

No documented work instructions
or training material available to
workers.



Head markings

Alloy Grade

Manufacturer Identification

Written Procedure for Electric Lead Connections

- Use only silicon bronze or stainless steel bolts for copper to copper connections
- Use lubricant and anti-seize components (e.g. moly disulphide for stainless steel)
- Use a calibrated torque wrench, torque to specification for hardware used and mark
- Test the joint with milli-Ohm meter

Bolt Size Inches or #	Threads Per Inch	Standard Dry Torque in Inch-Pounds					
		18-8 Stainless Steel	Brass	Silicon Bronze	2024-T4 Aluminum	316 Stainless Steel	Monel
1/4	20	75.2	61.5	68.8	45.6	78.8	85.3
	28	94.0	77.0	87.0	57.0	99.0	106.0
5/16	18	132	107	123	80	138	149
	24	142	116	131	86	147	160
3/8	16	236	192	219	143	247	266
	24	259	212	240	157	271	294
7/16	14	376	317	349	228	393	427
	20	400	327	371	242	418	451
1/2	13	517	422	480	313	542	584
	20	541	443	502	328	565	613

Facility for Rare Isotope Beams

FRIB-T31209-PR-000380-R002

Procedure for Tightening Hardware for Power Supply and Magnet Connections

Issued 24 March 2016

Procedure for Tightening Hardware for Power Supply and Magnet Connections

FRIB-T31209-PR-000380-R002



Issued 24 March 2016

Inspection of all Electrical Lead Connections

Before start of operations:

Test all electrical lead connections between magnets and power supplies at the Laboratory (459 superconducting and room temperature magnets)

- **Visual Inspection**
(you can see a lot by just looking)
- **Measurement of resistance with milli-Ohm meter**
- **Thermal imaging with infrared imaging system**
(operate magnet at high current and inspect temperatures of electric connections)



Summary

Failure of a bolt in an electric lead connection can lead to catastrophic results (particularly with super-conductive magnets)

- **Prepare written instructions for electric connections**
- **Buy quality hardware from reputable vendor**
- **Train your employees**
- **Inspect your connections on a regular basis**

\$5



\$500000