

AD collector: repairs in 2018 and mechanical considerations

F. Carra on behalf of EN-MME

AD Electron Cooler Consolidation Review

26/03/2019





- Introduction
- Collector design
- Weld repair
- Mechanical considerations
- Conclusions



Introduction

- 23rd July 2018: water leak to vacuum in the AD collector, replaced with a spare unit
- 6th September 2018: same issue to the spare collector.
- 21st September 2018: original unit repaired at the EN-MME workshop and made available to BE-BI
- 28th September: leaking spare unit replaced with repaired original collector





Courtesy of J. Cenede





F. Carra

Collector design





Collector design: end cover



- Two-walled cover, walls made of 316LN, welded circumferentially (upstream side: impacted by the electrons; downstream side: not impacted by the electrons)
- Cover is water cooled, at a pressure of 3.2 bar
- Cylindrical stiffeners added to decrease stresses and deformations on the two walls
- Stiffeners are EB-welded to the two sides of the cover (12 welds per side)
- Material of the stiffeners could not be determined with certainty (austenitic stainless steel, but which one?)



Mechanical considerations: finite elements model

- Analysis were performed in the EN-MME unit to estimate the stress levels in the welds
- Given the uncertainties in the materials, calculations were performed both for 304L and 316LN
- Only the stresses arising from the water pressure were evaluated (no residual stresses from welding, no electron-induced stresses)
- Operating temperature not known: material properties assumed at room temperature (no significant effect expected on elastic constants, but may be relevant for yield stress)

Material	Young's Modulus E [GPa]	Poisson's ratio <i>v</i> [-]	Yield Strength σ _y [MPa]	Ultimate Strength σ _R [MPa]
316LN v.p.	200	0.3	300	600
304L v.p.	200	0.3	220	520





Mechanical considerations: finite elements model

- Weld penetration assumed: 1.5 mm (original welds)
- 3.2 bar water pressure



Mechanical considerations: finite elements results

Cover deformation in the order of 0.5 mm

Mechanical considerations: finite elements results

Inner pin-Top cover weld

Weld

Bottom

Cover/Inner Pin

 Safety factors on stiffener welds not very reassuring, considering that only water pressure is taken into account and room temperature properties considered...

316LN

Safety factor

42.1

6.0

4.8

4.2

5.3

Max σ_{\perp} [MPa]

33

 Comparable stresses on both cover 	Top Cover/Bottom Cover	10	5
sides and on all stiffeners	Top Cover/Outer Pin	67	37
 Lowest safety factor is found at the position where the leak developed 	Top Cover/Inner Pin	83	47
	Bottom Cover/Outer Pin	95	38

76

Max σ_{Eq} [MPa]

304L

Safety factor

37.1

5.2

4.2

3.6

4.5

Weld repair

- Leak test performed at the main workshop to identify the leaking weld
- Welding parameters from the original piece were not available
- New procedure developed at the workshop, with tests on samples to optimize the welding parameters

Courtesy of M. Redondas

Welding tests on samples

F. Carra

Weld repair

- Decision to repair all the stiffeners/cover welds on the accessible side
- Weld repair duration: 1 day (in total ~1 working week for disassembling, leak detection, welding, reassembling).
- Weld penetration depth: 2.5 mm (the old one was 1.5 mm)
- Electron beam welding parameters:

```
WELDING PARAMETERS: Courtesy of M. Redondas
FIRST WELD ??
REPAIR: Focus current 1000/362 mA
60 kV ; 12 mm/s ; 12 mA
slope in 20° ; overlap 40° ; slope out 50°
REPAIR 2 (only 2 pins): Focus current 1000/360 mA
60 kV ; 12 mm/s ; 13 mA
Overlap opposite to first pass
```


Weld repair: caveat

- Additionally: not a standard butt weld, presenting potential risks of corrosion from cooling water in the interstice
- Only the accessible side of the cover was repaired! But: non negligible stresses also on the other side...
- Several welds!

Conclusions

- In September 2018, the leaking collector was repaired in the main workshop at EN-MME
- The leak was detected at the weld between one of the 12 stiffeners and the side of the cover impacted by the electrons
- To prepare for the repairing, two actions in parallel at EN-MME:
 - Weld tests on samples at the workshop to determine the best welding parameters
 - Mechanical calculations to determine the stress levels on the pin welds
- The distribution of stresses is similar on several pins → it was decided to repair all the welds on the accessible side of the cover
- Non negligible stress state on the welds and high number of welds between water and vacuum (25 in total for the cover) → design weak point, to be addressed in future design of the collector (*e.g.* take inspiration from the e-lens collector)
- This weak point is not easily removable in the 2nd existing spare collector (which also developed a leak in September 2018)

Thanks for your attention

Backup slides

Case 6 – CuCr1Zr load = 50kW

Advantage : T_{lim max} = 500 °C

Output:

- T_{max}^{-} Cu= 63 °C (bottom part of the collector)
- ΔT water = 16 °C
- v_{max} water bottom= 2.7 m/s is the max reached on the back part of the tube

	T max Cu	ΔT water
Cu v _{i water} = 1 m/s	57 °C	16 ºC
CuCr1Zr v _{i water} = 1 m/s	63 °C	16 ºC

			316LN	304L
Weld	Max σ_{Eq} [MPa]	Max σ [MPa] ⊥	Safety factor	Safety factor
Top Cover/Bottom Cover	10	5	42.1	37.1
Top Cover/Outer Pin	67	37	6.0	5.2
Top Cover/Inner Pin	83	47	4.8	4.2
Bottom Cover/Outer Pin	95	38	4.2	3.6
Bottom Cover/Inner Pin	76	33	5.3	4.5