





UNIVERSITÀ DEGLI STUDI DI MILANO

DIPARTIMENTO DI FISICA

# Performance of high-density indium bump-bonding

G. Alimonti<sup>(1)</sup>, A. Andreazza<sup>(1)</sup>, M. Antonello<sup>(1)</sup>, A. Carbone<sup>(1)</sup>, M. Daas<sup>(2)</sup>, F. Hügging<sup>(2)</sup>, S. Monzani<sup>(1)</sup>, F. Sabatini<sup>(1)</sup>, <u>B. Cervato<sup>(1)</sup></u>

<sup>(1)</sup> Dipartimento di Fisica Università di Milano and INFN Sezione di Milano <sup>(2)</sup> Physikalisches Institut Universität Bonn

### Flip-chip bump-bonding

- The bump-bonding techniques:
  - Electrically and mechanically connect sensor and front-end chip
  - Work at the contact density required for the ATLAS high granularity pixel detector (40 000 contacts/cm<sup>2</sup>, with a pixel size of 50 x 50  $\mu$ m<sup>2</sup>)
  - Two different bump-bonding technologies:
    - Solder bump (Sn-Ag)
    - Indium bump  $\Rightarrow$  analyzed in this presentation and poster
- Issues:
  - Planarity between FE and sensor during flip-chip
  - Deformations coming from internal stress of the chip Are critical parameters due to:
    - Large sensor and chip size (minimum size  $\sim 20 \times 21 \text{ mm}^2$ )
    - Low components thickness (100 250  $\mu m)$
    - Working temperature (~ 90° C for In bump)

#### It is necessary to estimate bump contacts failure!



#### Testing procedure and results

- I-V characteristics at different production stages show breakdown > 200 V
- Threshold and Time Over Threshold (ToT) tuning. If read-out electronics does not work as aspected ⇒ pixel is disabled
- 3) X ray (or radioactive source) show pixels with no hit. It is crucial to distinguish
  - Missing bump (pixel with bad or no bump connection)
  - Disabled pixel (masked during tuning scans)

 ✓ Measured failure rates (10<sup>-5</sup> for single-chip module and 8 x 10<sup>-4</sup> for dual-chip module) much better than ATLAS specifications (< 8 x 10<sup>-3</sup>)





## Backup

#### Indium bump-bonding production steps

