on behalf of the Diagnostics Group :

Nicolas Benoist Friederike Ewald Eric Plouviez leaving this year Julien Poitou left Benoit Roche Kees Scheidt Fouhed Taoutaou Laura Torino left Franck Uberto leaving this year BPMs

BLMs

**Emittance Monitors** 

**Tune Monitors** 

**Current Transformers** 


**Screen Monitors** 


**Visible Light extraction** 


Scrapers, Collimators

Striplines & Shakers


Feedbacks, Interloc












# **BPMS : PERFORMANCE AT COMMISSIONING AND BEYOND**


*historic event* : Thursday 28<sup>th</sup> November → first turns in the ring !!





# **BPMS AT EARLY COMMISSIONING : TURN-BY-TURN ORBIT**


*historic event* : Thursday 28<sup>th</sup> November → the orbit :






# **BPMS : OFFSETS, STABILITY, RESOLUTION, REPRODUCIBILITY, RELIABILITY**

Beam-Based-Alignment measurements done on all 320 units = ultimate offset\* measurement of each BPM in both planes  $\rightarrow$ \* including all kinds of offsets these offsets are *very reasonable* in value : Hor. 170um rms, Vert. 142um rms




BPM station

# BPMS : TODAYS BEAM AC MOTION / STABILITY WITH FOC OFF AND ON




# BPMS : AC MOTION : IN OLD RING AND IN EBS

Stability in the low-AC domain (1 – 100Hz)



# **BPMS: MID-TERM (90SEC) STABILITY IN THE ID-SECTIONS**






# **BPMS : PLANS**

- 1) carry-out a hardware patch on the electronics, by iTech removal / re-installation of all 320 units, during shutdowns, throughout 2020 (21 ?)
  - \* LNCF patch (see iTech presentation last year)
  - \* Tantalum capacitor replacement
- 2) occasional shot-circuits on BPM-buttons, but easy to detect, and easy to remedy, in total 20 cases so far (on 1300 buttons), this (well-known) issue is now waning off
- 3) strange behavior (instability) on some 7<sup>th</sup> BPMs, only in vertical plane, under investigation is not a problem for operation, these few stations can be discarded




# **STRANGE BEHAVIOR ON SOME 7TH BPMS**




this is NOT coherent ... ! i.e. it can NOT be explained by neither beam motion nor block motion

RF mode coupled to the buttons? adding to buttons' signals with different phases and amplitudes





# BLMS






### **BLMS : FIRST TURNS DETECTION**

#### *historic event* : Thursday 28<sup>th</sup> November $\rightarrow$ first turns in the ring !!


# raw output from 1 BLD unit







# 128 BLDs around the ring : very useful to detect obstacles ... !






# obstacle #2 : cell-8 : wrongly mounted chamber #10





#### obstacle #3 : cell-5 : a piece of aluminium foil

#### obstacle #3 : cell-5 : a piece of aluminium foil



# **BLMS : SERVING STUDIES OF LOCAL LOSSES AT IDS**

this 1rst unit is positioned behind the Insertion Device


and now serves more and more in the comparative (i.e. with 2018, old ring) studies of local losses in the IDs

- both for these permanent, slow losses

- but also for injection losses




### EMITTANCE MONITORS : X-RAY PINHOLE CAMERA SYSTEMS






# X-RAY PINHOLE CAMERA : SET-UP, PRINCIPLE, TYPICAL DIMENSIONS




# EMITTANCE MONITORS : EARLY AVAILABILITY

#### 6. December 2019 14h22, a few microAmps, NO pinhole inserted




#### 6 December 2019 16h15, 20 uA with pinhole IN





# **Tune Monitors**




all components in the system optimized to yield the maximum sensitivity

> horizontal stripline to <u>excite</u> the beam


diagnostic chamber Ch12 with pick-up buttons to <u>measure the</u> <u>response</u>



# **TUNE MONITORS : TWO INDEPENDENT UNITS**



# COLLIMATORS: 2 UNITS INSTALLED CELL 13 AND CELL 24





### COLLIMATORS : INSIDE CROSS-SECTION , STATUS

