

# CMS LS2 Beam-pipe upgrade Status update meeting 24/06/2020

Josef Sestak

TE-VSC-BVO

## Content

- Central beryllium chamber;
- Forward aluminum chambers;
- Structural supports;
- Bake-out and fibers;
- Optimization in 16 18m zone;

Points for discussion

- Forward assembly removal;
- Installation planning;



## Central beryllium chamber HCVC5C0038-MN000001

### Recent process and outlook

- Central chamber NEG coated;
- NEG performance tests;
- Expected "Ready for Installation" by July.

#### Foreseen activities with accepted chamber

- Pre-installation metrology;
- Installation of the fibers;
- Installation of the 1.6m collars;
- Survey test in b.113 with fully equipped chamber.

#### **Issues**

- No equipment related issues for the moment.
- Process (handling) issues during the NEG coating.
- Seals new series of seals is being tested; we have reliable solution with older type of seal.





## Forward aluminium chambers VC5F Forward chambers HCVC5F0010-CR\*

#### **Recent process and outlook**

- 3 chambers NEG coated and accepted;
- Ready for installation now.

#### Issues

- Short circuit on one of the heaters during NEG performance test.
- Faulty segment replaced by spare heater.





## Forward aluminium chambers VC5FP Forward pumping chambers HCVC5FP002-CR\*

### **Recent process and outlook**

- 3 chambers vacuum acceptance ongoing;
- 3 chambers NEG coating by next two weeks;
- 3 chambers NEG performance test by mid-July;
- Ready for installation by end of July;

#### **Issues**

- Mechanical problems with insertion of the RF screen
- Once solved mechanical damage of the screen ☺.











## Forward aluminium chambers HF-CT2 chambers (2+1) HCVC5HFCT1-CR\*

### Recent process and outlook

- Chamber #1 vacuum acceptance completed;
- Chamber #2 bake-out wrapping ongoing;
- Chamber #3 stand-by;

#### Issues

- On chamber #1 again short circuit during the bake-out
  - Probably related with the glue within the sandwich
  - We are starting with systematic test of all heaters.
- On chamber 1;3 a slight surface decolorization was observed; RGA spectrum OK; XPS shows sign of elevated silicon on the surface.

Surface issue discussed with chemistry & coating experts

Recommendation

We etch the chamber using circulation method before the NEG





## Forward aluminium chambers End-cap chambers (2+1) HCVC5E0035-CR\*

### Recent process and outlook

- Chamber #1 production completed stand-by;
- Chamber #2 production completed stand-by;
- Chamber #3 production completed stand-by;

#### Issues

- No equipment issues observed
- XPS samples from the final cleaning shows similar silicone contamination as for the HF-CT2.

Surface issue discussed with chemistry & coating experts

Recommendation

We etch the chamber using circulation method before the NEG





## Structural supports (codes LHCVH5\_%)

## Design of all operational supports completed;

- Supports at 3.2 and 3.5m to be checked by tracker team (LHCVH5\_\_0140; LHCVH5\_\_0168);
- Support interface 16 18m designed according to the agreed layout and ready for production;

#### Production

- Operation support at 1.6m (2parts collar) production completed;
- Operational support at 10.6m (new collar and Ti bar) in production;
- Support assembly 15.4 15.8m (Forward nose) in production;




## **Bake-out and fibers**


- Installation of the fibers after the NEG coating
- Please let us know about delivery dates and expected installation availability for all 3 types of chambers (central; HF-CT2; End-cap)
- Position of Lemo connectors TBD.


















## Advantages

- Reduced force load on 16m fix point from 850N (TAS) to 25N (IP5);
- Reduced force load on 18m fix point from 1420N (IP5) to 550N (IP5);
- Easier installation flexibility between forward and forward pumping;
- Reduced mass of 316L material;

## Implications

- Aperture restriction moves towards IP5 (no problem as aperture margin is sufficient at that position);
- Design modifications of 18m support minor;

6/24/2020

Production of a new components ≈ 8kCHF.



