## **ISOLDE Report FOM 2020/08/11** (Week from 08/04 to 08/10)

# ISOLDE low energy hardware commissioning:

- > Electrostatic quads and steerers polarity tests: all done except for
  - the 2 new front-end, not in place
  - the RBO line: damaged connectors need to be changed
- > Vacuum systems (J. Ferreira Somoza): progressing as planned
  - From Friday all Low energy lines are pumping. (too much outgassing in sector with the new tape station, and leak in CA10 sector)

# **REX/HIE-ISOLDE hardware commissioning:**

#### **▶** Beam instrumentation tests of:

- Voltage of the electron suppressor completed (All the FCs except for the three new ones)
- Gain for all the FCs
- Integration window
- Movement tests.
- **Pending issues:** Several devices don't respond to the movement requests. E. Bravin, S. Sadovich working on the problem.

### <u>Cryogenics and SRF</u> (W. Venturini, D. Valuch): progressing as planned


- The tunnel was opened on Thursday morning to carry out on CM4 for the installation of the solenoid leads (heaters and thermostats).
- Cool down of SC cavities continued

### <u>REXEBIS</u> (Fredrik Wenander, Gunn Khatri, M. Lozano Benito): progressing

- Optimization of the beam charge breeding in the REX-EBIS after injection from the REX-TRAP local ion source. Trap, BTS, EBIS and Separator tuned for 39K10+ and 208 mA electron beam.
- Several mass-scans of REXEBIS contaminants done to investigate the reason of poor efficiency.
- ➤ <u>Pending issues</u>. (Oasis support)

  TOF functionality (BTS.BO30 and RFQ.BO30) \_ XBTS.BO30-TOF-CH signal seems just noise

#### Pending issues Reported on July 28th



Intermittent glitches in the control system. All controls freeze for around five seconds. Observed from time to time but less of last week.