




ELENA beam commissioning status





Main results



- Setup LNA.USER.HMPROD1 for GBAR production beam
 - □ h=4 + bunch rotation (manual); ~100 ns FWHM beam
 - $\hfill\square$ Using re-matched **optics** by ABT
 - $\hfill\square$ Easily possible to steer the beam in the experiment with the dedicated knobs
- GBAR observed some first (partial) beam deceleration
 - Orbit drift observed between morning/evening on Wednesday, which was not visible elsewhere. No explanation so far.
- Source H₂ cartridges has been exchanged on Tuesday
- E-cooler **electron gun** cathode heated at nominal current over the week
- Advancements on tools for machine optimization
 - $\hfill\square$ Successfully tested prof-of-principle setup for new extraction timing with ~1 ms delay set on fast delays
 - Defined **knobs** and mastered **incorporation rules** for ions orbit optimization in the cooler
 - $\hfill\square$ Injection **oscillation** analysis
 - □ Scraper measurements
 - $\hfill\square$ Data taking for optics measurement from BPM turn-by-turn data

Not possible to pulse the ion switch => no beam to LNE00/ALPHA





- **iSeg power supplies** are still the week point of ion switch powering
 - \square Ion switch itself has been re-conditioned up to about 31.5 kV with no breakdowns
 - □ Attempt to use a **newer iSeg firmware failed**
 - □ Attempt to **pulse FUG power supplies** (**1Q**) showed that we would require some additional circuit (HV resistors?) to obtain a fast discharge, presently of ~13 s.
 - Solution being explored by EPC
 - □ Presently, **iSeg operational as before**, but **still using FUG** → will switch tomorrow for ALPHA beam test
- Cooling water circuit is common among the whole AD hall and has limited filtering capabilities
 - On Friday, by opening some AD circuit the conductivity increased and the Hsource tripped on overcurrent on the main HV circuit.
- Power converter limits are not easily predictable by LSA/cycle editor tools
 - $\hfill\square$ Working on cycle structure adjustement is lenghtening by settings inconsitencies
 - □ We need "**transactional**" trim from FGC_63, to **be deployed** and tested by EPC (January?)
- Baseline of LNE50.BSGW.5060 (vertical plane only) is still jumping
 - □ Investigation (Ion pump, electrostatic quad, valve/beam stopper) did not reveal any issue
 - □ Note: on Tuesday the baseline was jumping much less than usual
 - $\hfill\square$ Only 2 profile monitors in the line for Gbar beam alignement
- Time jitter of extracted beam:
 - □ ~20 ns rms jitter always present. Unclear source: unstable b-train? LLRF loop settings?