







Soldering tests of quench heaters (QH) Computed tomography (CT) imaging and metallurgical investigations

Mariusz Jedrychowski - Mickaël Crouvizier – Mickaël Meyer/Mechanical & Materials Engineering group, EN-MME-MM

Post-mortem analysis CR14



First inspection August 2020



11/27/2020



EN-MME-MM | 10RM18 – QH soldering tests – metallurgical investigations

Post-mortem analysis CR14





Post-mortem analysis CR14

Detailed report on last investigations EDMS 2431738





Reduced observable section → A significant part of the connector is missing
On the remaining observable section: indications of porosities, burnt organic compounds and mechanical tearing.

Post-mortem analysis CR14



Post-mortem analysis CR14



List of samples

Detailed report with all metallographic analysis EDMS 2424315

Sample reference	examined Sample #	Configuration	Tinning	Cleaning	Pickling
ES-AE	4 and 6; 5 ¹	Standard*	X	X	X
ES-SE	1 and 3; 2 ¹	Standard*		X	X
ENS-AE	1; 1 ¹	Standard*	X		
ENS-AE-DP	1 and 2; 3 ¹	Standard*	X		X (partial)
ENS-SE	1 and 2; 1 ¹	Standard*			
ENS-SE-DP	5 and 6; 4 ¹	Standard*			X (partial)
EGB-AE	2 and 3; 1 ¹	Standard**	X	X	X
EF-AE	5 and 6; 4 ¹	Wire on QH tape***	X	X	X
FCGB-SE	3 and 4; 2 ¹	Flat connector****		X	X
FCGB-SE with Omega	2 and 3; 1 ¹	Omega on flat connector		X	X

**with the 90° curved connector between the cable and the QH*

***with the 90° curved connector between the cable and the QH with the use of a dedicated tooling ensuring the geometry of the configuration*

****here the curved connector is not used, wires composing the cables are directly soldered on the QH tape*




*****pressure is applied on flat connector during soldering process*

¹for examination by computed X-ray micro tomography

EF-AE : Tinning, Cleaning, Pickling

No significant defects were found. **General good quality**, both connector and QH copper surfaces are in contact with the solder.

 4-EF-AE[frontView].avi (Command Line)



11/27/2020

EN-MME-MM | 10RM18 – QH soldering tests – metallurgical investigations


8

ES-AE : Tinning, Cleaning, Pickling

Minor defects were found (**QH tape embedded**), but overall the **quality** of the solder is good.



5-ES-AE[topView].avi (Command Line)





11/27/2020

EN-MMF-MM | 10RM18 - QH soldering tests - metallurgical investigations

ES-SE : Cleaning, Pickling

Overall the **quality of the solder is good**, but one big open pore was found in CT scan.







2-ES-SE[topView].avi (Command Line)



2-ES-SE[unrolledView].avi (Command Line)

EGB-AE : Tinning, Cleaning, Pickling







Large bonding imperfections due the presence of polyimide film.



11/27/2020

ENS-AE-DP : Tinning, Pickling



Reduced soldered interface due to embedded QH (arrows) and big void (CT scan).



3-ENS-AE-DP[frontView].avi (Command Line)

ENS-SE-DP : Pickling (partial)


Partial bonding due to the presence of polyimide film, large void under the solder.



4-ENS-SE-DP[frontView].avi (Command Line)



4-ENS-SE-DP[topView].avi (Command Line)










ENS-AE : Tinning

Solder is detached from QH copper tape.



1-ENS-AE[frontView].avi (Command Line)



Non-planar 1



206%

ENS-SE :without any preparation

Poor joint quality, the pin's connector is not soldered to QH copper tape



1-ENS-SE[topView].avi (Command Line)




11/27/2020


EN-MIME-MM | 10RM18 – QH soldering tests – metallurgical investigations

15

FCBG-SE (without pressure) :cleaning pickling






Sample 1




Sample 2


FCBG-SE with pressure






FCBG-SE with pressure




FCGB-SE #3 stitched picture, local depression at the solder due to pressure during soldering is visible (arrow)




FCGB-SE #4 stitched picture, local depression at the solder due to pressure during soldering is visible




FCBG-SE with Omega : cleaning pickling




FCBG-SE with Omega




FCGB-SE with Omega #2, large porosities and bonding imperfections are observed



FCGB-SE with Omega #3, large porosities and bonding imperfections are observed




large gas pockets are observed between connector and quench heater tape



large porosities are observed all around the connector




interface between the connector and the solder




interface between the connector and the QH

Soldered interfaces analysis (SEM-EDS)




Solder/QH tape interface (EF-AE#6)



All examinations showed the presence of Cu_xSn_y , absence of Ni_3Sn_4 and extremely limited copper diffusion in the solder.

Here, some representative analysis of all inspected samples.



Solder/wire interface (EF-AE#6)

Conclusion

To the extent of present analysis, the best configurations seems to be: **EF-AE**, **FGBG-SE** and **ES-AE**, **ES-SE**.

- Tinning seems to be not mandatory to reach good quality of bonding, cleaning and pickling steps are of key importance,
- The influence of tape's edges appears to be 1st order factor. The presence of polyimide film at the solder led systematically to bonding imperfections,
- **ENS-AE**, **ENS-SE** exhibit nonfunctional electrical connections.

Sample reference	Configuration	Tinning	Cleaning	Pickling
ES-AE	Standard*	X	X	X
ES-SE	Standard*		X	X
ENS-AE	Standard*	X		
ENS-AE-DP	Standard*	X		X (partial)
ENS-SE	Standard*			
ENS-SE-DP	Standard*			X (partial)
EGB-AE	Standard**	X	X	X
EF-AE	Wire on QH tape***	X	X	X
FCGB-SE	Flat connector****		X	X
FCGB-SE with Omega	Flat connector with copper Omega on it		X	X

Conclusion

SEM-EDS analysis showed that:

- copper diffusion from QH tape or from brass connectors is absent or extremely limited,
- Nickel layer, which acts as a barrier diffusion, is observed between copper layer and stainless steel of the QH tape but also at surface of brass connectors (protection against corrosion),
- Intermetallic compounds formed at soldered interface are Cu_xSn_y with multiple stoichiometry observed: mainly Cu_6Sn_5 and some Cu_3Sn to the extent of present analysis,
- No free tin (leading to potential whiskers with time) have been noticed at interfaces between prior tin plated wire or connector and solder.