# PT status and planning

Michael Pešek Charles University, Prague


### **Outline**


- Activities since last TB
- Planning
- Manpower

#### Activities since last TB

- Warming up the system
- <sup>3</sup>He pipe reinforcement welding week of 22<sup>nd</sup> November
- Leak detector maintenance
- 4He pumps maintenance
- Repair gate valve control cable connector
- Exchange <sup>3</sup>He gate valve coil
- Lab testing of the 2 new Gunn diodes

# <sup>3</sup>He pumping line reinforcement





Disconnected all pipes on the concrete wall To avoid possible electronics damage by leakage current from welding

Stiffening rings welded in place

<sup>&</sup>lt;sup>3</sup>He pumping line leak checked after reconnection, fixed gate valve control cable 08/02/2022 damaged during the operation




#### New features of the system:

- Internal reference 10MHz generator (no need for external generator)
- Control via USB/Ethernet/optical fibre
- Optical fibre/Ethernet converters to be purchased
- New control system

#### **Activities continued**

- Restart isolation vacuum pumping 2<sup>nd</sup> February some difficulties to restart due to water pressure sensor → resolved by EP-DT (bypass)
- Exchange <sup>3</sup>He pumps oil 3<sup>rd</sup> February
- Reconnect <sup>4</sup>He pumping line (new teflon seal) 4<sup>th</sup> Feb
- Leak-check <sup>4</sup>He pumps & new seal 4<sup>th</sup> Feb
- Exchange 1 <sup>3</sup>He gas panel valve (Tino Cryolab)
- <sup>3</sup>He pumps purging by N<sub>2</sub> gas ongoing
- <sup>3</sup>He circuit leak check ongoing

### Schedule for 2022



Preliminary planning Loading 15/3 → possibly shift by one week due to DSO tests in 888

## Manpower



Final confirmation expected for Jaakko Discussion ongoing with Dubna to fix the presence of experts Yamagata presence might be affected by travel restrictions

#### Conclusion

- PT preparation in full swing
- Schedule (well) defined
- Manpower availability is essential!

# **Spares**

## 3He valves





23/03/2021

3He gas panel



Replaced