
Effect of Injector kicker failure(s) on 28th July 2011



After the switch off the fraction of modules with drift speed from injector is unchanged