

# PSB DUMP ENDOSCOPY LIU-PSB Meeting


February 16, 2012 Alba Sarrió



#### Vacuum Pipe



### Dump core



BUT AWARSE STAT	178	· · · · · · · · · · · · · · · · · · ·	IV XC B
DEST NUMBERS SING	172	ļ	NU JU B
i	14	L	1
ARIOND ONDS TORREST ARION PART	11	A. 100. 18	X 250 41.08 20.00 1
MANERAL DOMES.	2	A. inc. 36	SUM 4108 54.200.1
COURSE COURSE FILLTY &	9	1.000× 376	92H 41.08 39 178 f
	18		Ĩ
CALL	7	A.	
TUBE AND	6	A. Age. JO	, .
TUBE DROFT	5	Acinon 304	
D00085 2 0 80	4	A	
asoust 100 860	3	Ac.	
DUGGE MATERIE	17	A. 100 500	
DEGUE AVANT	1/	A. 60% 334	5/2.8/
DISCOPTION	100	#. (927 334 HAT.	SVP, EJ, ORSERVA SIQUES
DISCOUTION Regard visitor Regards			
DISCOUTEDN Region visitate Regions	100	RAT. Tonkeyer	ORSERVA FIQUS
DISCOUTION Regard visitor Regards	100	RAT. Tombren	ORSERVA SIÇNS ADPLACE ADPLACE PAS AGRICACION
DISCRETTAIN  Second visuals begins  Second visuals begins  Second visuals by the second  Second visuals by the second by the sec	POS	NAT: Tonica	ORGERVASIONS ADRILACE ADRILACE PAR
DESCRIPTION    Bayon, 198 000 Bayonas   Costs   Costs	POS	NAT.	ORSERVA SOURS SOURCE PAS ASSOCIATION SOURCE PAS
DISCOUTTAN  Report 198 000 Reports  Group and reports (198 197 (198 198 197 (198 198 198 198 198 (198 198 198 198 (198 198 198 198 198 (198 198 198 198 198 198 198 (198 198 198 198 198 198 198 198 198 198	POS	NAT.	ORSERVA SIÇNS ADPLACE ADPLACE PAS AGRICACION
O 15 C 00 F 12 N   O 15 C 00 F	POS	NAT.	ORSERVA SOURS SOURCE PAS ASSOCIATION SOURCE PAS
DISCOUTTAN  Report 198 000 Reports  Group and reports (198 197 (198 198 197 (198 198 198 198 198 (198 198 198 198 (198 198 198 198 198 (198 198 198 198 198 198 198 (198 198 198 198 198 198 198 198 198 198	Pos		ORSERVA SOURS SOURCE PAS ASSOCIATION SOURCE PAS
015/00/100   015/000   015/00/100   015/00/100   015/00/100   015/00/100   015/00/100   015/000/100   015/000/100   015/000/100   015/000/100   015/	P05	867. 100kgm 1 17 + 61 0 8 62 0 2 12 1 22 145	ORSERVA SOURS SOURCE PAS ASSOCIATION SOURCE PAS
015/00/100   015/000   015/00/100   015/00/100   015/00/100   015/00/100   015/00/100   015/000/100   015/000/100   015/000/100   015/000/100   015/	P05		Onjetiva (r/m)  - Ohi/AC
O 15 C 00 F 12 N   O 15 C 00 F	P05		Ongenya (nyes)  FORMAT (PA)  FORMAT (PA)  Record (PA)  Re
Ottominas  Insuring and Section  Section (Section Section Sect	100	Half.  Total control c	Onjetiva (r/m)  - Ohi/AC
ottomas  Paragraphia	100	RAT	Ongenyanyang  Ongenyanyang  Terraci yan  Terraci yan  Montrean  Sani ang
0150mmas  otto 37500 begins  ott	IP .	RAT	Ongenya (nyes)  FORMAT (PA)  FORMAT (PA)  Record (PA)  Re




05/12/2011







### The endoscope



#### The endoscope



The endoscope



### Endoscopy



### Endoscopy



#### Protection for the head of the endoscope





#### Protection for the head of the endoscope



























BCN connection for the thermocouple?




BCN connection for the thermocouple?




BCN connection for the thermocouple?



BCN connection for the thermocouple?























By endoscope (picture of the screen)



By endoscope (picture of the screen)



By endoscope (picture of the screen)



By endoscope (picture of the screen)



By endoscope (picture of the screen)



By endoscope (picture of the screen)

#### **CONCLUSIONS**

- A new endoscopy needs to be done, with better equipment
  - Probably during next technical in April
  - A new endoscopy has been ordered
  - For the future, it will important to control the position of the camera (to know exactly the direction we are pointing at)
- It is clear that the dump was assembled rotated 180°. The real pictures don't match the drawings.
   Is there a way to understand why?
- On the videos it is possible to see the border in between concrete blocks.