




Collimation MP tests



- Executed 86 x 18 = **1548 tests in 2 days**
- Transfer Line + TDI ongoing
- Issues encountered and fixed:
 - IP8: the new, 1-beam TCTPV was still connected to 2 beam BICs (like to old 2-beam TCTVB)
 - 2 & 3-BIC for inj. prot. colls: not all OUT limits connected to inj. BIC and not all IN limits connected to ring BIC.









Participants: C. Bracco, A. Rossi, B. Salvachua, G. Valentino



Integration in AccTesting




- Collimators imported into AccTesting in Jan 2015, implemented as sign-only test for now
- For 2016 recommissioning:
 - aim to execute tests only from AccTesting (need to handle 2/3 BIC collimators..)
 - upload results to AccTesting instead of current (painful) MTF
- Suggestions: shorten test names, allow MCS-collimation role to also execute tests





Collimation MP tests



- RBAC: **OK**
- MCS-Collimation: OK after new release
- Collimator temperature tests: to be done
 - 90/731 tests failing
 - right of IP5 sensors appear not to be connected, CMW device N/A
- Crystal goniometer (verification of out-switch interlock, consignation of motors): **OK**
- Interlock response to power cut: to be done today
- Interlock response to PRS reboot: to be done today
- Local mode interlock: to be done today