




Fibre beam loss monitor test installation


Location: The first two cells after injection. This covers the collimators, several IDs and most of the beam pipe shape transitions.



Bench test
setup



First results



We can see things but will it make a useful monitoring system?