

- 1. ZS4 sparking problem gap increased
- 2. BLM's not firing beam dump. Saturday switched to software interlock. Sunday Hardware interlock restored.
- 3. Power glitch in BA2 provoked by cooling. Vacuum valve stuck in. Access to block it out.
- 4. RF power problem expert intervention needed.

Intensity on T6 gradually increased from 30 to 120 units

QF current loop rolled back to reduce noise on extraction.

