

Overview of the present SMP system

I. Romera Ramírez on behalf of TE-MPE-MI


21 June 2019 - Special MPP-SMP2 meeting



- SMP layout
- Evolution of the system since deployment
- Dependability in RUN1 and RUN2
- Motivation to upgrade



SMP Layout




Fast, safe and reliable



SMP Layout


CERN





Hardware


- Hardware based on VMEbus
- Physical separation of critical / monitoring
- Redundant implementation for high safety
- Common HW design for all SMP boards (CISR, CISG, CISA and CISC)






Hardware to receive SMP flags


- CISV is used to decode LHC-SMP flags distributed over the GMT
- CISV based on standard CTRV (BE-CO) with dedicated firmware maintained by TE-MPE
- **44 CISV boards in operation** (BIS, BLM, MKI, TCD, ATLAS, ALICE, CMS and LHCb)
- A hardware cross-check (CISC) ensures that no discrepancies are observed between SMP and GMT


















LHC: Cross-checker











LHC: SBF equations






SBF equations in RUN1


SBF equations in RUN2








SPS: Layout of BCTDCs since 2017






LHC: Layout of BCTDCs since 2017










SPS: TED flag

- TEDs will not be able to withstand a full 25 ns LIU batch consisting of 288b
- New machine protection strategy with LHC beams after LS2 (SPS-OTH-ES-0001)
- The maximum intensity to be extracted with TED in beam \leq 3.34 x 10¹³ protons
- Logic:

SPS_TBF = true when (SPS_INTENSITY $\leq 3.5 \times 10e13$)

else SPS_TBF = false

- SPS_TBF transmitted over the GMT and received via a standard timing board (CTR)
- 4 ELMA 3U VME chassis to be installed





Dependability in RUN1 and RUN2

- 2010 March Beam dump triggered by SBF B1-A going erroneously false for 100 ms (<u>MPP link</u>), which led to the replacement of the external SBF threshold board by internal ROM in the FPGA. Fixed!
- 2010 April Availability issues due to Beam Presence Flag oscillating. Intensity close to the threshold (<u>MPP link</u>). Not an SMP fault, BCT responsible for the flag generation. SMP retransmission only. BPF filter implemented on SMP.
- 2012 March Beam dump due to SBF B2 going false. Could not confirm the cause but hypothesis is that BCT B2 sent spurious high intensity value
- 2018 February Issues with transmission of SMP flags to GMT during HWC. Faulty cable, switched to spare cable
- 2018 July Redundant power supplies from laser transceivers (CIBF) preventively replaced to avoid availability issues



Motivation to upgrade

Obsolescence

- Discontinuity of critical electronic components Xilinx Spartan 2 / 3
- **Full occupancy** of FPGA logic cells no space for new features
- Aging of the present system -> support until end of HL-LHC
- Implementation of new requirements
 - Transmission of Energy and Intensity in the SPS
 - Transmission of bunch intensity in both SPS and LHC?
 - Implementation of TED flags in LS2 required optimization

See Raffaello's talk



Conclusions

- Dependability of the present SMP system was extremely good during the RUN1 and RUN2, in particular after the major firmware upgrade in 2012
- The broadcast of mission critical flags over the GMT was proven to be adequate and reliable, thanks to the implementation of a hardware crosschecker
- An upgrade of the system is needed to guarantee the long-term maintenance (including implementation of new requirements) and to follow the BIS developments



Thank you for your attention!

