



They are supposed to drill 11mm and use M10 HILTI bolts.

I specified 11mm on all the drawings:

