

Catania DOM integration site activities

9 12 2020 DOM Integration meeting

Emanuele Leonora

INFN, sezione di Catania








On-going activities: replacement of the penetrator type P on DOM 4.111



- Required maximum care
- Long and flexable tools to operate with PMTs mounted on TOP
- Safe and stable positions for inner cable before actions
- Main difficult with optical fiber treatment
- Thanks to Giusi La Rosa (LNS) for supporting the action on fibers
- Functional test was good, and we are going ahead with closure
- Shipment to DU integration foreseen for this Friday







		Т		T												
1	OM integration	INFN Catania		KM3NeT		DU line D								Date	09/1	2/20
K	DOM	522	524	525	526	527	528	529	530	531						
	SFP	СН20Н	CH22H	СН24Н	СН26Н	СН28Н	снзон	СН32Н	СН34Н	СН36Н						
	ending of deflect. rings	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
	ninting of the PMT tructuters (TOP & BOT)	ОК	ОК	ОК	ОК	ОК	ОК	OK	ОК	ОК						
	ing of P. gauge and moBeacon on TOP	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
	Piezo glued on BOTTOM	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
Mı	ushroom glued on TOP	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
E	lectronics in TOP	ОК*	OK*	ОК	ОК	ОК	ОК	ОК	ОК							
Po	enetrator on TOP	ОК	ОК	ОК	ОК	ОК	ОК	ОК								
	Helium test	ОК	ОК	ОК	ОК	ОК	ОК	ОК								
8A	kD filter routed on fiber tray	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
opt	tical splice and test	ОК	ОК	ОК	ОК	ОК	ОК									
PM	Ts in TOP structure	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
Р	MTs in BOTTOM structure	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
i	BOTTOM instrumentation	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК	ОК						
F	unctionality test	ОК	ОК	ОК	ОК	ОК	ОК									
G	Gluing of the TOP structure on mushroom	ОК	ОК	ОК	ОК	ОК	ОК									
Ge	el pouring on TOP	ОК	ОК	ОК	ОК	ОК	ОК									
	Gel pouring on BOTTOM	ОК	ОК	ОК	ОК	ОК	ОК									
Cl	osure and sealing with collar	ОК	ОК	ОК	ОК	ОК	ОК									3
4	Acceptance test	OK*	OK*	ОК	ОК	ОК	ОК									


DOM integration	INFN Catania		KM3NeT		DU line A		Under work								Date 09/12/20			
DOM	544	545	546	547	548	549										559	560	561
SFP	CH56C	CH54C	CH52C	CH50C	CH48C	CH46C										CH26C	CH24C	CH22C
Bending of deflect. rings	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Painting of the PMT structuters (TOP & BOT)	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Gluing of P. gauge and NanoBeacon on TOP	OK	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Piezo glued on BOTTOM	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Mushroom glued on TOP	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Electronics in TOP	OK*	OK*																
Penetrator on TOP	ОК	ОК																
Helium test	ОК	ОК																
A&D filter routed on fiber tray	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
optical splice and test	ОК	ОК																
PMTs in TOP structure	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
PMTs in BOTTOM structure	ОК	ОК	OK	ОК	ОК	ОК										ОК	ОК	ОК
BOTTOM instrumentation	ОК	ОК	ОК	ОК	ОК	ОК										ОК	ОК	ОК
Functionality test	ОК	ОК																
Gluing of the TOP structure on mushroom	ОК	ОК					_ D	ОМ 4	1.544	has been sent to								
Gel pouring on TOP	ОК	ОК					_ G	ENO\	/A in	JUN	2020)						
Gel pouring on BOTTOM		ОК									_ 	_						
Closure and sealing with collar	OK	OK																
Acceptance test	OK*	OK*																4



Next actions in program







- ✓ Replacement of Penetrator type P from one DOM = currently on-going.
- After the shipment and inspection of 36 DOMs we have several NCR to be open...
- ☐ Re-building of the TOP of the DOM 9 form ARCA DU 39. CLB and PB have been removed for not functionality. They will be sent to Valencia for inspection
- ☐ Going ahead with DOM production
- ☐ White Rabbit Switch implementation for the DAQ system (new guy in the group)
- Upgrading the softwares needed for DOM test and analisys (new guy in the group)