Comments and observations

M. Alexeev & colleagues Università di Torino & INFN Torino





2

## Works on MWPCs during the winter period

- We are evaluating to refurbish from 1 (PA01) to several MWPCs
- For the operations we need the stretching machine and the space in the clean area
- Most probably we will be able to start the repair operations in February but preparations could start in 2021
- If there will be no accidents we would need ~1 week / 1,5 chamber
- Mylar (with laminated Al) availability is still somehow a problem






#### **RW** interventions

2500

2000

1500

- We have mounted and put in operation all the FEs but 1, that has a broken Hotlink, waiting for the a spare
- The wrong channels ordering has been corrected by a new mapping
- We are still facing some noise and gas distribution (we hope not leaks) issues
- A screening on all the channels will be installed during the winter stop
- We will update the gas distribution panel for a better control on the gas flux







### Common tracking station @ PRM test


- No information on the status of the common vessel
- The mechanics for the ALPIDE part are in production and are expected to arrive between this week and 15.10
- The FE cards:


#### <u>AMUX</u> – is being submitted

<u>Transition board</u> – has been submitted but the company informed (27.09.21) that due to a illness of personnel will not be able to fulfil the deadline. Presently resubmitting to a different company, assembly to be made at CERN

<u>CMUX</u> – has been produce, firmware in development









- ALPIDE carrier cards has been promised, no other ALPIDE is available
- A test DAQ based on MOSAIC RO cards (help form GSI) is being assembled at CERN
- We might have help from GSI, York University people but need to understand if the could be part of any eventual publication of the results

# iFTDC FE for MWPC

- We have most of the equipment ready do be assembled
- Some preliminary preparation will take place during the next MD
- Production of the final cabling is expected to be concluded before the 06.10
- Modification to the monitoring software has been started
- We need to understand how the thresholds and the configuration will be loaded into the FEs
- Reconstruction software shall be updated
- The remote monitoring of the PS is not working properly, investigating



