QPS signals on PIC display

Signal exchange between QPS and PIC

PIC - Scada Server   CMW   QPS - (Scada Server x 8)

Display

Continuous data update for each Circuit OK

Ask to Give Permit / Circuit

Request to QPS

Signal with Time-Stamp = ST_PWR_PERMIT

Give or Remove Permit

Ethernet: technical network

PLC

DQGTW

Profibus

WorldFIP

Remote I/O

DQAMG   DQAMS

Signal exchange status… 28/10/2005

- **Status**
  - PVSS CMW driver in beta version
  - PIC supervision Interface ready

- **Has to be done:**
  - Addresses mapping (PIC & QPS Scada servers)
  - ST_PWR_PERMIT calculation in QPS Scada servers
    - Many QPS agents on several GTW
    - Data quality
  - Functionality tests
  - Time estimation to get ST_PWR_PERMIT on request