Special MPP
LINAC4 Machine Protection

Friday 29 July 2016

- Review Objectives
  - Overview of system architecture
  - What interlock functionality is currently implemented?
  - How will it have to be modified for the half-sector test?
  - What interlock functionality is still missing (both for the half-sector test and final configuration)?
  - Has the interlock functionality been validated? When and how?

- Indico https://indico.cern.ch/event/557965/

- 50MeV Commissioning Preparation
  - https://indico.cern.ch/event/404834/
- 50 MeV Commissioning Experience
  - https://indico.cern.ch/event/447582/
- 100MeV Commissioning Preparation
  - https://indico.cern.ch/event/507450/