Steps

- Detailed 3D model (Ok)

- Simplification to obtained representative model of the volume under vacuum (Ongoing)

- Add information to the model. Experimental information available.

- Implement modifications in layout and re-calculate