

# Injector Technical Stop Schedule

## Cool-down:

- Wed. 21.04 @ 1:30: Stop proton beams > 200e10 charges/cycle
- Wed. 21.04 @ 5:30: Stop proton beams < 200e10 charges/cycle

## RP Survey:

- Wed. 21.04 @ 07:30: Start RP survey in all machines

## Technical stop:

- Wed. 21.04 @ 08:00: L4, PSB, PS, SPS start TS
- Thu. 22.04 @ 12:00: L4, PSB, PS SWY end TS
- Thu. 22.04 @ 17:00: PS, SPS end TS