

How to improve turn-around

Wednesday 8 December 2010 09:00 (25 minutes)

Where did we lose time (injection, ramp, squeeze, etc.). What can we do to minimize that (in the LHC and injectors)?

Critical review of the operational procedures

Squeeze: what can be improved? shall we still consider the option of a combined ramp and (partial?) squeeze?

What are the implications of that: setting-up time, controls, reliability, machine protection. Impact on collimation, feedbacks

Presenter: REDAELLI, S.

Session Classification: Session 2: Driving the LHC