

HMPID to do list for the  
beam test w43

# Review of the to do list

- Complete the reconstruction code in O2. In Alice only HMPID is missing this task (A. Morsh conversation).
- Hoping the new C-RORC firmware fixing the backpressure at the beginning of the run will be put in place;
- Review the detector configuration (pedestal run, pedestal uploading...)
- RICH4 at nominal HV 2000V and current peaks observed during the TED shots oct 08
- QC status enough for the pilot beam?

# Review of the to do list

- Service work updating for 2022-projection 2023
- Messages to service workers: Lazslo and Paz;
- What about to ALICE-Ba?