

Injection Kicker MKI-D Field Breakdown

- April 15, 04:47: Injection failure
 - Appears oscillations on partially kicked train was worst on second turn
 - **BCM : Equivalent to 3×10^7 MIPs / cm^2 !! (centre of shower)**
 - 144 bunches on TDI lead to equivalent of 2×10^5 MIPs / cm^2 (April 18)
 - **Factor 100 above dump threshold at injection**
 - A problem with the TDI alignment is a major worry

