

1- How to generate a section view from a broken view (“Callout”)

(Link: [Knowledge base - Mechanical Design](#))

2- Implementation of a 3D “rib”(winding coil & civil engineering)

(Link: [Knowledge base - Mechanical Design](#))

3- Re-organize a Part list after a “BOM Compare”

(Link: [Knowledge base - Smarteam](#))

The screenshot shows the CERN CAD Service Knowledge Base. The top navigation bar includes links for EDMS Service, CAD Service, CMMS Service, Home, Services, Support, Training, Methodology, FAQ, GUCS, Knowledge Base (which is highlighted with a yellow box), and Discussions. The main content area shows a list of topics under the 'Mechanical Design' category. Each topic includes a subject line, a 'Workbench' column (e.g., Drafting, Assembly Design, Part Design, Sketcher), and a 'Replies' column (e.g., 0, 1). A large yellow arrow points to the 'Mechanical Design' heading, and another yellow arrow points to the 'Knowledge Base' tab in the navigation bar.

Subject	Workbench	Replies
Importer lignes dans un plan	Drafting	0
Exporter et utiliser le resultat d'une section	Assembly Design	0
Objet non connex	Part Design	0
Symétrie d'un assemblage	Assembly Design	0
Générer une section à partir d'une vue brisée	Drafting	0
Ajouter un attribut type masse dans la mise en plan:	Drafting	0
Ranger les composants et les contraintes d'un assemblage.	Assembly Design	1
Ajouter des cotes 3D dans la 2D	Drafting	0
Manque taraudage/filetage dans plan	Drafting	1
1 seul trait d'axe par Sketch	Sketcher	0
Creer tunnel suivant courbe qui monte et tourne en gardant le sol horizontal	Part Design	0
Remplacer une maquette par une autre dans un plan,sans refaire tout le plan	Part Design	0
How updating hatchings which do not match to the standard material selected	Drafting	0
The "callout" is red in a detail you have created	Drafting	0
Creating a new part from an existing one present in the standard catalog	Part Design	0
How finding easily an inertia center?	Part Design	0
How to generate new CATPart from a CATPart already included in an CATProduct open in your catia session	Part Design	0
creer une Part depuis une part standard (save as)en coupant le lien avec la table de paramétrage	Part Design	0
lignes qui n'apparaissent pas sur un plan.	Drafting	0

Add new discussion

Infrastructure

Subject

There are no items to show in this view of the "Infrastructure" discussion board. To create a new item, click "Add new discussion" below.

Add new discussion