

Inspection of the electron dump

- After 133 days of operation (2021): no sign of damage
- Plus 50 days of operation in 2022 : still no sign of damage or degradation. Marks have appeared, due to electron impact. Two very tiny spots, that do not impact the operation. Under analysis

