



Spotted inconsistencies between BIM Model 07/04/2022 and reality on-site

Amélie Meyer, Ludovic Barthelemy, Angel Navascues Cornago

30/08/2022



US57 – North side Mezzanine

On the model :

- Free space between the vault from the right of the platine to the walkway : 16cm
- 50 cm further (thickness of the cable tray) : 12cm

On-site :

- 13.5cm
- 7cm




US57 – South side mezzanine

On the model :

- Length of the handrail :

On-site :

- Length of the L handrail : 95cm x 54cm
- Distance between the crinoline and the vault : 138cm



Solution proposed

Moving/modifying metal plates from the walkway to save space


Distance between the platine and HEB100: 16.5 cm

Possibility of cutting the metal plates to **gain at least 3cm** of free space



Metallic support for cable trays

Would be installed after December 2022 **by others**





home.cern