



*Technical
Infrastructure*

Tue 08/11/22 16:44

Level 3 alarm "Hydrogen leak" and evacuation of EHN1. Fire Brigade on-site, it was a false alarm caused by manipulations done by users of the experiment.

Wed 09/11/22 18:43

Evacuation alarms in SPS 4,5,6 et ECA5. ([AFT 762476](#))

- Fire Brigade confirmed an alarm on one of the evacuation buttons in the tunnel. Since no access was given since a long time (nobody possibly present in the tunnel), the alarm was reset remotely, but the reset did not work.
- SPS interlock on a kicker magnet (fire alarm) seems to be a consequence of the evacuation alarm (interlock?)
- Alarm was reset locally by Fire Brigade, but the ventilation for the air extraction of the BA5 beam dump couldn't restart. This was due to a problem with a flow meter that didn't allow for the restart.

Sun 13/11/22 01:42

Fire alarm SFDEI-56504 in SPS PA6. Evacuation BA5, BA6, BA1 triggered. (AFT 765033)

- Ventilation of BA6 stopped.
- On site, 10 sensors are showing elevated readings but not enough to go into alarm. No evidence of smoke.
- The ventilation had a mechanical problem that caused the smoke, it was left off for the weekend and repairs ~~will be planned as soon as possible~~ were done, a bearing was replaced.