


RD50-MPW3 - Lab measurements



UNIVERSITY OF
LIVERPOOL


Samuel Powell

RD50-MPW3 S-curves




- Distinct difference between top and bottom of matrix suspected to be due to a TrimDac config being applied unknowingly

RD50-MPW3 S-curves



RD50-MPW3 S-curves



- Modifying the trimDac Config file has solved the issue. Scans ongoing...

RD50-MPW3 S-curves

