



Octant 4 Integration Study

Ovoid Fire Door

D. del Álamo – EN-ACE-INT

08-05-2024

OCTANT 4 - OVOID

Reminder




Current Situation



OCTANT 4 - OVOID

Reminder



Current Situation

OCTANT 4 - OVOID


Reminder



The door should not block the sewer access.

OCTANT 4 - OVOID


Reminder



Due to the traverse cable tray, the fire door should be pushed further away.

OCTANT 4 - OVOID


Reminder



Not visible in the 3D model, the cable tray support should be avoided or moved.

OCTANT 4 - OVOID

Reminder





Have the cable been removed?

OCTANT 4 – FIRE DOOR

Do we have a 3D model or the general dimensions of the fire door?

OTHER OCTANCTS – FIRE DOOR





**ENGINEERING
DEPARTMENT**

home.cern