



Contribution ID: 6

Type: **not specified**

## Controls Changes

*Wednesday, 18 January 2006 11:15 (20 minutes)*

What changes have been made for that will affect PS SPS Operation, application SW, timing and sequencing. What actions have been undertaken to ensure that we can restart PS and SPS correctly? Any other issues related to the very long stop

**Presenter:** SICARD, Claude-Henri

**Session Classification:** Session 1: What Has Been Done