


# QA Si sensor Test Stand University of Rochester

- o Setup was idle 7 years since 2007
- o Probe station during some period of time was used for 4point resistivity tests
- o Sept 2014 the setup is reinstalled and full strip test was performed on STM OB1 30210334420027.



September 18, 2014

US Silicon Tracker group  
University of Rochester

# CONCLUSIONS


- Hardware and software both are operational (work as expected)
- Probe tips have to be changed and will be replaced when necessary



September 18, 2014

US Silicon Tracker group  
University of Rochester

OB1 30210334420027



September 18, 2014

US Silicon Tracker group  
University of Rochester


4



September 18, 2014

US Silicon Tracker group  
University of Rochester


# IV Test



September 18, 2014

US Silicon Tracker group  
University of Rochester


# CV Test



September 18, 2014

US Silicon Tracker group  
University of Rochester

# Istrip Test




September 18, 2014

US Silicon Tracker group  
University of Rochester



# Rpoly Test




September 18, 2014

US Silicon Tracker group  
University of Rochester



# Idiel Test



September 18, 2014

US Silicon Tracker group  
University of Rochester

11

# Summary STM OB1 30210334420027

- Hardware and software both are operational (work as expected)
- Probe tips have to be changed and will be replaced when necessary