

2014 Injector Accelerator Schedule

Preliminary

	Jan					Feb			Mar				
Wk	1	2	3	4	5	6	7	8	9	10	11	12	13
Mo	30	6	13	20	27	3	10	17	24	3	10	17	24
Tu													
We			SHUTDOWN LS1							PSB and PS access system commissioning (plus HW testing as appropriate)			
Th													
Fr													
Sa													
Su													

	Apr			May				June						
Wk	14	15	16	17	18	19	20	21	22	23	24	25	26	
Mo	31	7	14	Easter Mon	21	28	5	12	19	26	2	9	16	23
Tu														
We														
Th					1st May									
Fr			G. Friday											
Sa				PSB/PS hw tests, control system tests dry runs etc.			PSB cold checkout PS hardware tests							
Su								First beam possible into PS zone		PSB setup with beam PS cold checkout				PS setup with beam

	July			Aug				Sep					
Wk	27	28	29	30	31	32	33	34	35	36	37	38	39
Mo	30	7	14	21	28	4	11	18	25	1	8	15	22
Tu													
We													
Th													
Fr													
Sa													
Su													

	Oct			Nov				Dec					
Wk	40	41	42	43	44	45	46	47	48	49	50	51	52
Mo	29	6	13	20	27	3	10	17	24	1	8	15	22
Tu													
We													
Th													
Fr													
Sa													
Su													

HighRadMat: possible beam request