


17-21 Jan 2005



Workshop Chamonix XIV

Session 4 - Other Issues affecting Beam Commissioning I

CERN, 503/1-001 - Council Chamber

Tuesday 18 January

14:00

Session 4 - Other Issues affecting Beam Commissioning I

Session | Location: CERN, 503/1-001 - Council Chamber | Conveners: Rhodri (Scientific Secretary) Jones, Stephan (Chairman) Russenschuck

14:00-14:20 Electrical Quality Assurance (ELQA)

Speaker

Mr Davide Bozzini

Location

CERN, 503/1-001 - Council Chamber

14:25-14:45 Report from the Magnet Polarity Coordinator

Speaker

Dr Stephan Russenschuck

Location

CERN, 503/1-001 - Council Chamber

14:50-15:10 Quench Protection System

Speaker

Reiner Denz

Location

CERN, 503/1-001 - Council Chamber

15:15-15:35 Consequences of RF system failures during LHC beam commissioning.

Speaker

Dr Trevor Linnecar

Location

CERN, 503/1-001 - Council Chamber

15:40-16:00 Coffee break

16:00-16:20 Initial commissioning of critical beam instrumentation systems

Speaker

Dr Eva Barbara Holzer

Location

CERN, 503/1-001 - Council Chamber

16:25-16:45

The estimation of individual and collective intervention doses for the LHC beam cleaning insertions

Speaker

Markus Brugger

Location

CERN, 503/1-001 - Council Chamber

16:50-17:10 The LHC Access System: why do we put doors?

Speaker

Dr Luigi Scibile

Location

17:30

CERN, 503/1-001 - Council Chamber