

without SVC, 0.75 % with SVC)


ating load

74 % with SVC)

Measurements after installation



harmonic distortion



Results of 18 kV harmonic measurements:

- **Total Harmonic Distortion** **0.74 %**
- **no individual harmonic exceeding** **0.5 %**

The measurements correspond closely to the calculated values.