FOCUS COIL STATUS

OXFORD V. Blackmore

> J. Cobb W. Lau

RAL V. Bayliss J. Boehm T. Bradshaw M. Courthold R. Preece

J. Tarrant

M. Tucker

S. Watson MICE PPS Searched Area

Entry Restricted. Access by Permit to Work only

Contact

ICE Ops' Ma

October 2015

DARESBURY S. Griffiths T. Hartnett I. Mullacrane A. Oates P. Owens C. White

1/20

FC Status MPB




HISTORY

- FC 1 did not train to full current
 - But remembered training
- FC2 had thermal shorts on arrival
 - Returned to Tesla & repaired
 - Tested in R9
 - Thermally slightly marginal
 - Trained much better than FC1
- FC2 chosen for Step IV in preference to FC1
 - Maximum current required
 - (Now known as FCU)

FCU COMMISSIONING

- Did not cool down properly June / July
 - Confusing story
 - Many & various opinions / hypotheses / theories
 - Calculations
 - Warm up
 - Gas analysis
 - Move cryocoolers to shorten hoses
 - Pump & purge
 - Discussions with Tesla
- Second cool-down started September 11
 - Looked good thermally
 - Better than R9
- Electrical testing started 14 October

NOMINAL CURRENT SOLENOID MODE ON 22 OCTOBER



- Temperatures & He pressure behaved normally
 - like testing in R9
- No spikes on voltage traces


October 2015

STILL TO DO

- Minor electrical items including:
 - Adjustment of quench detector system
 - Allow for extra length of link between coils
 - Currently rather sensitive
- Soak test in solenoid mode
 - 24 hrs at 120 Amps
- Evaluate effect of running with asymmetric SSs
 - Asymmetric forces on cold mass
 - Requires calculations

TO BE DECIDED

- In consultation with stakeholders
 - MICE, project management..., optics experts....



- Find limit of Solenoid Mode
 - Never quenched in this mode (up to 120 A)
 - Expect ~85% of Flip Mode maximum ~ 190A
- Test in Flip Mode

