

1. PROM tests

- **DCFEB firmware downloading**
 - Failure rate ~10%
- **DCFEB PROM unused blocks test**
 - Probes ~70% of the PROM
 - Ran on all system
 - Found only 3 boards with issues
 - To be investigated in more detail
- **CHARM irradiation test**
 - Irradiated 2 boards with 32P + 128X to ~30kRad
 - First tests after the irradiation
 - Board #1 had no JTAG communication
 - Board #2 had bitflips, could not program 32P, could not erase 128X
 - Found dead LDO on board #1 and so-so regulator on board #2
 - After LDO replacement
 - Board #2: 32P PROM looks ok
 - Erase, blank check OK
 - Program, verify OK
 - Board #2: 128X PROM -- still cannot erase
 - Board #1: JTAG OK after Petrs “tricks”, PROMs not tested yet