





High latency instability at flat top (fill 6068, 300b)



- Some individual bunches became unstable (B1H) after 20 minutes at flat top
- Different bunches started oscillating at different time according to the HT monitor
- Similar to fill 5664 at the beginning of the year