



Wednesday stop for POPS card exchange: No trips since and timing reboot: ion inhibit OK

Wednesday afternoon irradiation in Charm could start. High intensity beam sent. Difficult to finish the EAST Xe beam set-up:

- 4 cameras broken during the set up. Access done on Tuesday to replace one
- Screen in Charm broken (compressed air movement)

Yesterday dedicated ion MD and access of over 1h to replace an amplifier for 10MHz C46 but the issue is not yet solved. Another access is required.

Ions sent to SPS: extracted 1.5×10^{10} charges. COLDEX beam prepared for Monday morning, vertical instability.