

Remarks on Maintenance

- ▶ New manual veto key installed on rack in service area
(never remove it !)
 - ▶ Jet to be included in access system view, and GifCS.
 - ▶ Currently only visible in the rack itself
(and as “Fault” in the CR)
 - ▶ REMUS detectors are now part of the interlock chain
 - ▶ Detection of high radiation in open access (Free/Key) will trigger evacuation alarm & VETO2 which needs to be RESET by CCC
 - ▶ NEVER change access to Key/Free within 5 seconds of turning OFF the source ! (Integration time of REMUS)
-
- ▶ UPS installed for GIF controls. Please DON'T turn OFF the controls inside the CR unless authorised by us.
 - ▶ No problem could be found on restarting the Irradiator. Was it set to “MAN” ?
 - ▶ Installation of cosmic roof chambers postponed. Needs new time slot.
 - ▶ Proposal : After first beam time when we remove CMS-DT MB2 (open roof) ?

