

SPS status

- Physics started on Monday 19:00 (instead of 8:00). Problems with beam loss monitors during weekend and Monday during the daytime.
- Tuesday scheduled stop for interventions in NA from 9:00 to 11:00. Beam only back around 14:30 because of RF (broken module)
- BLM problem still under investigation (general in all transfer lines). For TT20 the problem is under control but not yet completely operational.