


Machine status



- RF lemo issue has disturbed all beams several times during the past week. Cavity return sum signal distributed to all beam controls affected
- Two accesses for C51 and C76 Tuesday and Friday last week respectively
- EAST beams perturbed and cut for a while due to a connection problem in the 1553 bus affecting the power converters of the F61 and ZT line

Beam status

- Operational beams OK
 - TOF@730e10p now. Changed injection from R2 to R3 to avoid losses in PSB until TS1
- Beams for LHC MD slot OK
- Beam requests ready
 - LHC 50ns 36 and 12b now set up to be tested in SPS
 - LHC100#18b can be taken with 12 bunches too as requested
- In preparation
 - Ions 200ns 2b in work