

Linac3

- Monday: The 400kV power went down in the evening, and the decision was taken later in the evening not to make a restart.
- When the OK was give on Tuesday, the beam was back within 4 hours (from a cold start).
- Friday: One of the source power converters (IP.SOLEXT) tripped twice and could not easily be restarted. It required adjustment of the filter parameters. Each trip required an hour long reconditioning of the source.
- Saturday: A source performance change started around 13:30, and it took until around 21:00 to get back to a stable situation (with both ovens now being powered, a change in the source tuning point required).

Linac3

- *Thanks to everyone who helped make a success for Run2 for Linac3.*