

Workshop Chamonix XV

Monday, 23 January 2006

Session 02 - The minimum workable LHC - machine protection and collimation (14:00 - 17:30)

time	[id] title	presenter
14:00	[86] Commissioning and (early) operation - view from machine protection	UYTHOVEN, Jan
14:25	[62] What Systems request a Beam Dump	WENNINGER, Jorg
14:50	[67] What is required to safely fill LHC	KAIN, Verena
15:15	Coffee Break	
15:40	[85] What is required to get the beam safely out of LHC	GODDARD, Brennan
16:05	[88] Beam Commissioning of the Collimation Systems	ASSMANN, Ralph
16:30	[87] Critical Beam Losses during Commissioning and Initial Operation	ROBERT-DEMOLAIZE, Guillaume
16:55	[14] Commissioning of Beam Loss Monitors	DEHNING, Bernd