

Comment of Julien Palluel

The 2.5V and 5V regulators are now measured online in CNGS because we saw they get lower with radiation on the first repeater.

For the moment it works well, but we see only 4.5V and 2.05V (!) on the irradiated repeater (250Gy last year).