

NP04 Schedule 2020 ver. 1.0



Sep

Oct


Nov

Wk	40	41	42	43	44	45
Mo	Survey 28	Remove beam line 5	12	19	26	2
Tu	AUG test (no access)	Cut Cher. Gas lines	Remove CRT	Test cold box + noise in the APA		Cryostat empty (forecast) but probably still too cold
We	Free area pit	Remove Beam Platform				
Th						
Fr	VIC	Cut Cher. Gas lines as much as possible				


Empty platform



CRT storage



CRT storage



CRT storage

