

NP04 Schedule 2020

Christmas break

The chart illustrates the weekly schedule for NP04 from November 16 to December 21, 2020. The days of the week are listed vertically on the left, and the weeks are numbered across the top. Colored boxes represent different work phases, and specific tasks are noted within these boxes.

Wk	Nov 16	Nov 23	Nov 30	Dec 7	Dec 14	Dec 21
Mo		TCO: start removal Inner part		TCO: removal (t.b.c. in 2021)		
Tu	Positioning CRT					
We	Pump dry air in insulation	cold box consolidation work				
Th			cold box commissioning			
Fr						